0/29/2014 16:21:26 Page 1 of 2 Document Types: IR, LER From 01/01/2010 to 12/31/2010	U.S. Nuclear Regulatory Human Factors Information IR/LER Category Analysis by	System (HFIS) Docket Report 2	Total Number of Hits:27National Average:302x National Average:60National Median:18verage for Selected Dockets:27			
Facility Name: Beaver Valley 1 Docket (050- 00334)						
Details	Department	Work Type	Docket/Report			
Communication / IR						
160 - No communication / information not communicated Number of Items for this Docket: 1 Percent of Total for this Docket: 4	O - Operations	O - Control Room Ops	050-00334/2010-502			
Procedures & Reference Document / IR						
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00334/2010-004			
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00334/2009-005			
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00334/2010-004			
 111 - Procedure / reference document technical content Number of Items for this Docket: 4 Percent of Total for this Docket: 15 	P - Procedure Writers	P - Procedure Dev	050-00334/2009-005			
Training / IR						
102 - Individual knowledge LTA Number of Items for this Docket: 1	O - Operations	O - Control Room Ops	050-00334/2010-502			
Percent of Total for this Docket: 4						
Work Planning & Practices / IR						
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003			
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00334/2009-005			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003			
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2010-502			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2009-005			
186 - Failure to take action / meet requirements	P - Procedure Writers	P - Procedure Dev	050-00334/2009-005			
191 - Team interactions LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003			
Number of Items for this Docket: 8 Percent of Total for this Docket: 30						
Problem Identification & Resolution / LER						
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00334/2011-002-01			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01			
142 - Operating experience (OE) review LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01			
150 - Programmatic deficiency	O - Operations	O - Control Room Ops	050-00334/2011-002-01			

I0/29/2014 16:21:26 Page 2 of 2 Document Types: IR, LER From 01/01/2010 to 12/31/2010	U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report		Total Number of Hits:27National Average:302x National Average:60National Median:18Average for Selected Dockets:27			
Facility Name: Beaver Valley 1 Docket (050- 00334)						
Details	Department	Work Type	Docket/Report			
Problem Identification & Resolution / LER						
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01			
Number of Items for this Docket: 5 Percent of Total for this Docket: 19						
Training / LER						
102 - Individual knowledge LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01			
102 - Individual knowledge LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01			
Number of Items for this Docket: 2 Percent of Total for this Docket: 7						
Work Planning & Practices / LER						
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2011-002-01			
187 - Action implementation LTA	G - Engineering	G - Design	050-00334/2011-002-01			
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01			
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01			
Number of Items for this Docket: 6 Percent of Total for this Docket: 22						