10/09/2008 15:03:11 Page 1 of 2 Document Types: IR, LER From 01/01/2007 to 12/31/2007	U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report		Total Number of Hits:18National Average:412x National Average:82National Median:24Average for Selected Dockets:18		
Facility Name: Crystal River 3 Docket (050- 00302)					
Details	Department	Work Type	Docket/Report		
Communication / IR 160 - No communication / information not communicated Number of Items for this Docket: 1 Percent of Total for this Docket: 6	G - Engineering	G - Design	050-00302/2007-002		
Procedures & Reference Document / IR 110 - No procedure / reference documents Number of Items for this Docket: 1 Percent of Total for this Docket: 6	M - Mechanical	M - Maintenance / Repair	050-00302/2007-003		
Problem Identification & Resolution / IR					
140 - Problem not completely or accurately identified	O - Operations	S - Surveillance	050-00302/2007-002		
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00302/2007-002		
Number of Items for this Docket: 2 Percent of Total for this Docket: 11					
Work Planning & Practices / IR					
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00302/2006-005		
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00302/2006-005		
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00302/2006-005		
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00302/2006-005		
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00302/2006-005		
187 - Action implementation LTA	G - Engineering	G - Design	050-00302/2007-002		
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00302/2006-005		
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	S - Surveillance	050-00302/2007-002		
194 - Housekeeping LTA Number of Items for this Docket: 9 Percent of Total for this Docket: 50	M - Mechanical	M - Maintenance / Repair	050-00302/2007-002		
Oversight / LER					
 130 - Inadequate suprevision / command and control Number of Items for this Docket: 1 Percent of Total for this Docket: 6 	G - Engineering	M - Maintenance / Repair	050-00302/2007-002-00		
Problem Identification & Resolution / LER					
140 - Problem not completely or accurately identified	G - Engineering	M - Maintenance / Repair	050-00302/2007-002-00		
142 - Operating experience (OE) review LTA	Q - Quality assurance / oversight	W - Assessment	050-00302/2007-001-00		

0/09/2008 15:03:11 age 2 of 2 rocument Types: IR, LER rom 01/01/2007 to 12/31/2007	U.S. Nuclear Regulatory Com Human Factors Information Sys IR/LER Category Analysis by Do	tem (HFIS) I cket Report 2x I	Total Number of Hits:18National Average:412x National Average:82National Median:24Average for Selected Dockets:18	
	Facility Name: Crystal River 3 Dock	et (050- 00302)		
Details	Department	Work Type	Docket/Report	
Problem Identification & Resolution / LER				
144 - Audit / self-assessment / effectiveness review LTA	Q - Quality assurance / oversight	W - Assessment	050-00302/2007-001-00	
Number of Items for this Docket: 3				
Percent of Total for this Docket: 17				
Work Planning & Practices / LER				
186 - Failure to take action / meet requirements	G - Engineering	M - Maintenance / Repair	050-00302/2007-002-00	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 6				