10/09/2008 15:23:15

Page 1 of 2

Document Types: IR, LER From 01/01/2007 to 12/31/2007

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 19
National Average: 41
2x National Average: 82

National Median: 24
Average for Selected Dockets: 19

Details	Facility Name: Summer Docket (050- 00395)		
	Department	Work Type	Docket/Report
Oversight / IR			
30 - Inadequate suprevision / command and control	O - Operations	S - Surveillance	050-00395/2007-004
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
rocedures & Reference Document / IR			
11 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00395/2007-002
Number of Items for this Docket: 1 Percent of Total for this Docket: 5			
roblem Identification & Resolution / IR			
40 - Problem not completely or accurately identified	E - Electrical	M - Maintenance / Repair	050-00395/2007-002
40 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00395/2007-004
42 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00395/2007-002
48 - Action not yet started or untimely	G - Engineering	G - Design	050-00395/2007-002
50 - Programmatic deficiency	E - Electrical	M - Maintenance / Repair	050-00395/2007-002
Number of Items for this Docket: 5			
Percent of Total for this Docket: 26			
Vork Planning & Practices / IR			
85 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00395/2007-003
85 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00395/2007-002
85 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00395/2006-005
85 - Procedural adherence LTA	O - Operations	S - Surveillance	050-00395/2006-005
85 - Procedural adherence LTA	O - Operations	S - Surveillance	050-00395/2007-004
86 - Failure to take action / meet requirements	M - Mechanical	Q - Fire Protection	050-00395/2007-006
86 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00395/2007-004
96 - Independent verification / plant tours LTA	O - Operations	B - Bal of Plant Ops	050-00395/2007-004
Number of Items for this Docket: 8			
Percent of Total for this Docket: 42			
luman-System Interface & Environmnt / LER			
73 - Physical conditions LTA	O - Operations	V - Troubleshooting	050-00395/2007-002-00
Number of Items for this Docket: 1 Percent of Total for this Docket: 5			

10/09/2008 15:23:15

Page 2 of 2

Document Types: IR, LER From 01/01/2007 to 12/31/2007

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 19
National Average: 41
2x National Average: 82

National Median: 24

Average for Selected Dockets: 19

Details	Facility Name: Summer Docket (050- 00395)		
	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	I - Instrumentation & Control	T - Testing	050-00395/2007-003-00
Number of Items for this Docket: 1 Percent of Total for this Docket: 5			
Work Planning & Practices / LER			
186 - Failure to take action / meet requirements	O - Operations	V - Troubleshooting	050-00395/2007-002-00
190 - Failure to stop work / non-conservative decision making	O - Operations	V - Troubleshooting	050-00395/2007-002-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			