10/09/2008 15:27:51

Page 1 of 2

Document Types: IR, LER From 01/01/2007 to 12/31/2007

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 26
National Average: 41
2x National Average: 82
National Median: 24

Average for Selected Dockets: 26

	Facility Name: Turkey Point 3 Docket (050- 00250)		
Details	Department	Work Type	Docket/Report
Communication / IR			
162 - Communication Equipment LTA	O - Operations	S - Surveillance	050-00250/2007-004
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Fitness for Duty / IR			
125 - Work hour control	E - Electrical	M - Maintenance / Repair	050-00250/2007-004
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L'	G - Engineering	G - Design	050-00250/2007-003
Number of Items for this Docket: 1 Percent of Total for this Docket: 4			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	G - Engineering	S - Surveillance	050-00250/2006-005
140 - Problem not completely or accurately identified	I - Instrumentation & Control	M - Maintenance / Repair	050-00250/2007-003
140 - Problem not completely or accurately identified	O - Operations	S - Surveillance	050-00250/2007-004
142 - Operating experience (OE) review LTA	G - Engineering	S - Surveillance	050-00250/2006-005
146 - Evaluation LTA	G - Engineering	S - Surveillance	050-00250/2006-005
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00250/2006-005
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00250/2007-003
148 - Action not yet started or untimely	O - Operations	S - Surveillance	050-00250/2007-004
Number of Items for this Docket: 8 Percent of Total for this Docket: 31			
Work Planning & Practices / IR			
180 - Scheduling and planning LTA	E - Electrical	M - Maintenance / Repair	050-00250/2007-004
181 - Inadequate staffing / task allocation	E - Electrical	M - Maintenance / Repair	050-00250/2007-004
185 - Procedural adherence LTA	M - Mechanical	T - Testing	050-00250/2007-004
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00250/2007-006
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00250/2007-004
186 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00250/2007-004
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00250/2007-002
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00250/2007-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00250/2007-003

10/09/2008 15:27:51 Page 2 of 2

Document Types: IR, LER From 01/01/2007 to 12/31/2007

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 26
National Average: 41
2x National Average: 82

National Median: 24

Average for Selected Dockets: 26

Facility Name: Turke	ey Point 3 Docket ((050- 00250)
----------------------	---------------------	--------------

	racinty Name. Turkey Form 3 Dock	ity Name. Turkey Forit 3 Docket (030- 00230)		
Details	Department	Work Type	Docket/Report	
Work Planning & Practices / IR				
186 - Failure to take action / meet requirements	Q - Quality assurance / oversight	A - Administrative	050-00250/2007-004	
186 - Failure to take action / meet requirements	Y - Shipping / transportation	Y - Shipping / transportatic	050-00250/2007-004	
186 - Failure to take action / meet requirements	Z - Other / Unknown	T - Testing	050-00250/2007-003	
187 - Action implementation LTA	G - Engineering	Q - Fire Protection	050-00250/2007-006	
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	S - Surveillance	050-00250/2007-003	
197 - Self-check LTA	Y - Shipping / transportation	Y - Shipping / transportatic	050-00250/2007-004	
Number of Items for this Docket: 15				
Percent of Total for this Docket: 58				