05/29/2009 10:01:12 Page 54 of 226

Document Types: IR, LER From 01/01/2008 to 12/31/2008

Total Items for this Docket: 14

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

National Average: 35

2x National Average: 70

National Median: 21

		Average for S	Average for Selected Dockets: 35	
Facility Name: Diablo Canyon 1 Docket (050- 00275)				
Details	Department	Work Type	Docket/Report	
Human-System Interface & Environmnt / IR				
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00275/2007-005	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 7				
Oversight / IR				
130 - Inadequate suprevision / command and control	O - Operations	O - Control Room Ops	050-00275/2007-005	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 7				
Procedures & Reference Document / IR				
113 - Procedure / reference document development and maintenance L'	A - Administrative Support	P - Procedure Dev	050-00275/2007-005	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 7				
Problem Identification & Resolution / IR				
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00275/2007-005	
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00275/2007-005	
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00275/2007-005	
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00275/2007-005	
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00275/2007-005	
147 - Individual corrective action LTA	D - Emergency Planning	Q - Fire Protection	050-00275/2008-002	
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00275/2007-005	
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00275/2007-005	
Number of Items for this Docket: 8 Percent of Total for this Docket: 57				
Work Planning & Practices / IR				
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00275/2008-002	
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00275/2007-005	
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00275/2007-005	
Number of Items for this Docket: 3 Percent of Total for this Docket: 21				