U.S. Nuclear Regulatory Commission 05/29/2009 10:01:12 Total Number of Hits: 3662 Human Factors Information System (HFIS) Page 80 of 226 National Average: 35 Document Types: IR, LER **IR/LER Category Analysis by Docket Report** 2x National Average: 70 From 01/01/2008 to 12/31/2008 National Median: 21 Average for Selected Dockets: 35 Facility Name: Hatch 1 Docket (050-00321) Work Type Details Docket/Report Department Communication / IR 160 - No communication / information not communicated M - Mechanical M - Maintenance / Repair 050-00321/2008-008 160 - No communication / information not communicated M - Mechanical M - Maintenance / Repair 050-00321/2008-008 Number of Items for this Docket: 2 Percent of Total for this Docket: 8 Human-System Interface & Environmnt / IR 170 - HSI or information availability / quality LTA M - Mechanical M - Maintenance / Repair 050-00321/2008-004 170 - HSI or information availability / quality LTA M - Mechanical M - Maintenance / Repair 050-00321/2008-008 Number of Items for this Docket: 2 Percent of Total for this Docket: 8 **Oversight / IR** 131 - Management expectations or directions LTA O - Operations O - Control Room Ops 050-00321/2007-005 Number of Items for this Docket: 1 Percent of Total for this Docket: 4 Procedures & Reference Document / IR R - Refueling 111 - Procedure / reference document technical content F - Fuel Handling 050-00321/2008-002 113 - Procedure / reference document development and maintenance L' F - Fuel Handling R - Refueling 050-00321/2008-002 113 - Procedure / reference document development and maintenance L M - Mechanical M - Maintenance / Repair 050-00321/2008-008 Number of Items for this Docket: 3 Percent of Total for this Docket: 12 Problem Identification & Resolution / IR 140 - Problem not completely or accurately identified M - Mechanical M - Maintenance / Repair 050-00321/2008-008 142 - Operating experience (OE) review LTA M - Mechanical M - Maintenance / Repair 050-00321/2008-008 145 - Causal development LTA M - Mechanical M - Maintenance / Repair 050-00321/2008-008 146 - Evaluation LTA M - Mechanical M - Maintenance / Repair 050-00321/2008-008 148 - Action not yet started or untimely M - Mechanical M - Maintenance / Repair 050-00321/2008-008 Number of Items for this Docket: 5 Percent of Total for this Docket: 20 Work Planning & Practices / IR M - Mechanical 183 - Pre-job activities LTA M - Maintenance / Repair 050-00321/2008-002 185 - Procedural adherence LTA M - Mechanical F - Modification 050-00321/2008-002 185 - Procedural adherence LTA O - Control Room Ops O - Operations 050-00321/2007-005 186 - Failure to take action / meet requirements M - Mechanical F - Modification 050-00321/2008-003

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits:3662National Average:352x National Average:70National Median:21

Average for Selected Dockets: 35

	Facility Name: Hatch 1 Docket (050- 00321)		
Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00321/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00321/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00321/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00321/2008-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00321/2008-008
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00321/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00321/2008-008
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00321/2008-004
Number of Items for this Docket: 12			
Percent of Total for this Docket: 48			
Total Items for this Docket: 25			