05/29/2009 10:01:12 Page 179 of 226 Document Types: IR, LER From 01/01/2008 to 12/31/2008	U.S. Nuclear Regulator Human Factors Informatio IR/LER Category Analysis	on System (HFIS) by Docket Report 2x			
Facility Name: San Onofre 3 Docket (050- 00362)					
Details	Department	Work Type	Docket/Report		
Human-System Interface & Environmnt / IR					
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00362/2008-003		
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00362/2008-006		
Number of Items for this Docket:   2     Percent of Total for this Docket:   9					
Procedures & Reference Document / IR					
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00362/2008-003		
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00362/2008-003		
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00362/2008-006		
Number of Items for this Docket: 3 Percent of Total for this Docket: 14					
Problem Identification & Resolution / IR					
146 - Evaluation LTA	G - Engineering	G - Design	050-00362/2008-003		
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00362/2008-003		
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00362/2008-003		
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00362/2008-006		
Number of Items for this Docket:4Percent of Total for this Docket:18					
Work Planning & Practices / IR					
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00362/2008-003		
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00362/2008-003		
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00362/2008-003		
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00362/2008-003		
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00362/2008-006		
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00362/2008-003		
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00362/2008-006		
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00362/2008-003		
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00362/2008-003		
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00362/2008-006		
Number of Items for this Docket:10Percent of Total for this Docket:45					

05/29/2009 10:01:12 Page 180 of 226 Document Types: IR, LER From 01/01/2008 to 12/31/2008	U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report		Total Number of Hits:3662National Average:352x National Average:70National Median:21Average for Selected Dockets:35		
	Facility Name: San Onofre 3 Docket (050- 00362)				
Details Oversight / LER	Department	Work Type	Docket/Report		
130 - Inadequate suprevision / command and control   Number of Items for this Docket: 1   Percent of Total for this Docket: 5	O - Operations	O - Control Room Ops	050-00362/2008-005-00		
Procedures & Reference Document / LER 111 - Procedure / reference document technical content Number of Items for this Docket: 1 Percent of Total for this Docket: 5	O - Operations	S - Surveillance	050-00362/2008-007-00		
Work Planning & Practices / LER 186 - Failure to take action / meet requirements Number of Items for this Docket: 1 Percent of Total for this Docket: 5	P - Procedure Writers	P - Procedure Dev	050-00362/2008-007-00		
Total Items for this Docket: 22					