03/16/2015 17:34:36

Page 1 of 2

Document Types: IR, LER From 01/01/2010 to 12/31/2010

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 17
National Average: 30
2x National Average: 60

National Median: 18

Average for Selected Dockets: 17

Facility Name: Oyster Creek Docket (050- 00219)			
Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	M - Mechanical	M - Maintenance / Repair	050-00219/2009-005
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00219/2010-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 12			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00219/2010-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00219/2010-002
113 - Procedure / reference document development and maintenance L	P - Procedure Writers	P - Procedure Dev	050-00219/2010-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 12			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00219/2010-002
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00219/2010-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00219/2009-005
Number of Items for this Docket: 3			
Percent of Total for this Docket: 18			
Work Planning & Practices / IR			
180 - Scheduling and planning LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2009-005
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2009-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00219/2010-002
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00219/2010-002
186 - Failure to take action / meet requirements	L - Licensing / regulatory affairs	A - Administrative	050-00219/2010-002
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00219/2010-002
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00219/2010-002
191 - Team interactions LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2009-005

03/16/2015 17:34:36

Page 2 of 2

Document Types: IR, LER From 01/01/2010 to 12/31/2010

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 17
National Average: 30
2x National Average: 60

National Median: 18

050-00219/2009-005

Average for Selected Dockets: 17

M - Maintenance / Repair

Facility Name: Oyster Creek Docket (050-00219)

Details Department Work Type Docket/Report

M - Mechanical

Work Planning & Practices / IR

192 - Work untimely

Number of Items for this Docket: 9
Percent of Total for this Docket: 53

Total Items for this Docket: 17