

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 20

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 20

Facility Name: Farley 2 Docket (050- 00364)

Details	Department	Work Type	Docket/Report
Communication / IR			
161 - Communication LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
161 - Communication LTA	Z - Other / Unknown	Z - Other / Unknown	050-00364/2006-009
Number of Items for this Docket: 2			
Percent of Total for this Docket: 10			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00364/2005-005
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
Number of Items for this Docket: 2			
Percent of Total for this Docket: 10			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	I - Instrumentation & Control	M - Maintenance / Repair	050-00364/2005-005
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00364/2006-009
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
111 - Procedure / reference document technical content	M - Mechanical	S - Surveillance	050-00364/2006-009
113 - Procedure / reference document development and maintenance L	A - Administrative Support	A - Administrative	050-00364/2006-003
Number of Items for this Docket: 5			
Percent of Total for this Docket: 25			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
143 - Tracking / trending LTA	M - Mechanical	S - Surveillance	050-00364/2006-009
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
Number of Items for this Docket: 5			
Percent of Total for this Docket: 25			
<hr/>			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00364/2006-003
187 - Action implementation LTA	M - Mechanical	T - Testing	050-00364/2006-009
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00364/2006-009

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 20
National Average: 43
2x National Average: 86
National Median: 24
Average for Selected Dockets: 20**

Facility Name: Farley 2 Docket (050- 00364)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
190 - Failure to stop work / non-conservative decision making	M - Mechanical	T - Testing	050-00364/2006-009
Number of Items for this Docket: 6			
Percent of Total for this Docket: 30			

Total Items for this Docket: 20
