

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 37

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 37

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
160 - No communication / information not communicated	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	Q - Quality assurance / oversight	Y - Shipping / transportatic	050-00348/2007-010
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00348/2006-005
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00348/2007-008
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00348/2007-008
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-005
143 - Tracking / trending LTA	S - Specialized task force	W - Assessment	050-00348/2007-008
145 - Causal development LTA	S - Specialized task force	W - Assessment	050-00348/2007-008
146 - Evaluation LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-005
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00348/2007-008
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00348/2007-008
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-005
150 - Programmatic deficiency	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00348/2006-005
Number of Items for this Docket: 14			
Percent of Total for this Docket: 38			
<hr/>			
Training / IR			
100 - Training LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 37

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 37

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Training / IR			
102 - Individual knowledge LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-002
185 - Procedural adherence LTA	Y - Shipping / transportation	Y - Shipping / transportatic	050-00348/2007-010
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00348/2007-008
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00348/2007-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00348/2007-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00348/2007-008
188 - Work practice or craft skill LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
188 - Work practice or craft skill LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-010
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-002
193 - Non-conservative action	M - Mechanical	M - Maintenance / Repair	050-00348/2007-002
Number of Items for this Docket: 11			
Percent of Total for this Docket: 30			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	E - Electrical	T - Testing	050-00348/2007-001-00
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00348/2007-003-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Training / LER			
100 - Training LTA	O - Operations	S - Surveillance	050-00348/2007-003-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
Work Planning & Practices / LER			
187 - Action implementation LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-003-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 37
National Average: 41
2x National Average: 82
National Median: 24
Average for Selected Dockets: 37

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / LER			
189 - Recognition of adverse condition / questioning attitude LTA	E - Electrical	M - Maintenance / Repair	050-00348/2007-001-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			

Total Items for this Docket: 37
