10/09/2008 15:17:57

Page 1 of 3

Document Types: IR, LER From 01/01/2007 to 12/31/2007

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 47
National Average: 41
2x National Average: 82

National Median: 24

Average for Selected Dockets: 47

	Facility Name: Prairie Island 1 Docket (050- 00282)		
Details	Department	Work Type	Docket/Report
Oversight / IR			
130 - Inadequate suprevision / command and control	B - Management	W - Assessment	050-00282/2007-006
131 - Management expectations or directions LTA	B - Management	W - Assessment	050-00282/2007-006
Number of Items for this Docket: 2 Percent of Total for this Docket: 4			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00282/2007-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00282/2007-004
Number of Items for this Docket: 2 Percent of Total for this Docket: 4			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	E - Electrical	M - Maintenance / Repair	050-00282/2007-007
140 - Problem not completely or accurately identified	H - Health Physics	W - Assessment	050-00282/2007-006
140 - Problem not completely or accurately identified	H - Health Physics	W - Assessment	050-00282/2007-006
140 - Problem not completely or accurately identified	H - Health Physics	W - Assessment	050-00282/2007-006
140 - Problem not completely or accurately identified	H - Health Physics	W - Assessment	050-00282/2007-006
140 - Problem not completely or accurately identified	H - Health Physics	W - Assessment	050-00282/2007-006
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00282/2007-006
142 - Operating experience (OE) review LTA	G - Engineering	S - Surveillance	050-00282/2007-006
142 - Operating experience (OE) review LTA	H - Health Physics	W - Assessment	050-00282/2007-006
144 - Audit / self-assessment / effectiveness review LTA	Q - Quality assurance / oversight	W - Assessment	050-00282/2007-006
145 - Causal development LTA	H - Health Physics	W - Assessment	050-00282/2007-006
145 - Causal development LTA	H - Health Physics	W - Assessment	050-00282/2007-006
146 - Evaluation LTA	G - Engineering	G - Design	050-00282/2007-007
146 - Evaluation LTA	H - Health Physics	W - Assessment	050-00282/2007-006
146 - Evaluation LTA	H - Health Physics	W - Assessment	050-00282/2007-006
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00282/2007-007
147 - Individual corrective action LTA	H - Health Physics	W - Assessment	050-00282/2007-006
148 - Action not yet started or untimely	E - Electrical	F - Modification	050-00282/2007-007
148 - Action not yet started or untimely	H - Health Physics	H - Health Physics	050-00282/2007-002
Number of Items for this Docket: 19 Percent of Total for this Docket: 40			

10/09/2008 15:17:57

Page 2 of 3

Document Types: IR, LER From 01/01/2007 to 12/31/2007

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 47
National Average: 41
2x National Average: 82

National Median: 24

Average for Selected Dockets: 47

Facility Name: Prairie Island 1 Docket (050- 00282)				
Details	Department	Work Type	Docket/Report	
Work Planning & Practices / IR				
184 - Tag outs LTA	M - Mechanical	M - Maintenance / Repair	050-00282/2007-003	
185 - Procedural adherence LTA	G - Engineering	F - Modification	050-00282/2007-006	
185 - Procedural adherence LTA	G - Engineering	W - Assessment	050-00282/2007-006	
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00282/2006-005	
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00282/2006-005	
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00282/2007-003	
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00282/2007-007	
186 - Failure to take action / meet requirements	S - Specialized task force	W - Assessment	050-00282/2007-006	
187 - Action implementation LTA	G - Engineering	G - Design	050-00282/2007-007	
187 - Action implementation LTA	G - Engineering	G - Design	050-00282/2007-007	
187 - Action implementation LTA	O - Operations	W - Assessment	050-00282/2007-006	
187 - Action implementation LTA	S - Specialized task force	W - Assessment	050-00282/2007-006	
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00282/2007-002	
188 - Work practice or craft skill LTA	M - Mechanical	S - Surveillance	050-00282/2007-004	
189 - Recognition of adverse condition / questioning attitude LTA	D - Emergency Planning	D - Emergency Drill	050-00282/2007-004	
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	F - Modification	050-00282/2007-007	
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	T - Testing	050-00282/2007-007	
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00282/2007-007	
196 - Independent verification / plant tours LTA	G - Engineering	S - Surveillance	050-00282/2007-006	
196 - Independent verification / plant tours LTA	M - Mechanical	M - Maintenance / Repair	050-00282/2007-003	
196 - Independent verification / plant tours LTA	O - Operations	S - Surveillance	050-00282/2007-006	
Number of Items for this Docket: 21 Percent of Total for this Docket: 45				
Procedures & Reference Document / LER				
110 - No procedure / reference documents	M - Mechanical	Z - Other / Unknown	050-00282/2007-003-01	
111 - Procedure / reference document technical content  Number of Items for this Docket: 2  Percent of Total for this Docket: 4	S - Specialized task force	W - Assessment	050-00282/2007-003-01	

10/09/2008 15:17:57

Page 3 of 3

Document Types: IR, LER From 01/01/2007 to 12/31/2007

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 47
National Average: 41
2x National Average: 82
National Median: 24

Average for Selected Dockets: 47

Facility Name: Prairie Island 1 Docket (050-00282)

Details Department Work Type Docket/Report

Problem Identification & Resolution / LER

140 - Problem not completely or accurately identified S - Specialized task force W - Assessment 050-00282/2007-003-01

Number of Items for this Docket: 1 Percent of Total for this Docket: 2

Total Items for this Docket: 47