0/09/2008 15:22:09 Page 1 of 2 Document Types: IR, LER From 01/01/2007 to 12/31/2007	U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report Average		Total Number of Hits:17National Average:412x National Average:82National Median:24age for Selected Dockets:17		
	Facility Name: Sequoyah 1 Docket (050- 00327)				
Details	Department	Work Type	Docket/Report		
Communication / IR					
 160 - No communication / information not communicated Number of Items for this Docket: 1 Percent of Total for this Docket: 6 	M - Mechanical	M - Maintenance / Repair	050-00327/2007-004		
Procedures & Reference Document / IR					
110 - No procedure / reference documents	E - Electrical	M - Maintenance / Repair	050-00327/2007-006		
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00327/2006-005		
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00327/2007-006		
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00327/2007-006		
Number of Items for this Docket: 4 Percent of Total for this Docket: 24					
Problem Identification & Resolution / IR					
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00327/2007-002		
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00327/2006-005		
Number of Items for this Docket: 2 Percent of Total for this Docket: 12					
Training / IR					
101 - Training process problem	O - Operations	O - Control Room Ops	050-00327/2006-005		
101 - Training process problem	O - Operations	O - Control Room Ops	050-00327/2006-005		
101 - Training process problem	O - Operations	O - Control Room Ops	050-00327/2006-005		
101 - Training process problem	O - Operations	O - Control Room Ops	050-00327/2006-005		
Number of Items for this Docket: 4 Percent of Total for this Docket: 24					
Work Planning & Practices / IR					
180 - Scheduling and planning LTA	M - Mechanical	M - Maintenance / Repair	050-00327/2007-004		
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00327/2006-005		
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00327/2007-004		
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00327/2007-004		
187 - Action implementation LTA	G - Engineering	G - Design	050-00327/2007-006		

0/09/2008 15:22:09 age 2 of 2 ocument Types: IR, LER rom 01/01/2007 to 12/31/2007	U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report		Total Number of Hits: 17 National Average: 41 2x National Average: 82 National Median: 24 Average for Selected Dockets: 17	
	Facility Name: Sequoyah 1	Docket (050- 00327)		
Details	Department	Work Type	Docket/Report	
Work Planning & Practices / IR				
187 - Action implementation LTA	G - Engineering	G - Design	050-00327/2007-006	
Number of Items for this Docket: 6				
Percent of Total for this Docket: 35				