05/29/2009 10:01:12 Page 13 of 226

Document Types: IR, LER From 01/01/2008 to 12/31/2008

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Braidwood 2 Docket (050- 00457)						
Details	Department	Work Type	Docket/Report			
Communication / IR						
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00457/2008-004			
Number of Items for this Docket: 1 Percent of Total for this Docket: 6						
Procedures & Reference Document / IR						
113 - Procedure / reference document development and maintenance L'	I - Instrumentation & Control	H - Health Physics	050-00457/2008-002			
113 - Procedure / reference document development and maintenance L'	I - Instrumentation & Control	T - Testing	050-00457/2008-002			
Number of Items for this Docket: 2 Percent of Total for this Docket: 12						
Problem Identification & Resolution / IR						
146 - Evaluation LTA	G - Engineering	F - Modification	050-00457/2008-004			
146 - Evaluation LTA	G - Engineering	G - Design	050-00457/2007-006			
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00457/2007-006			
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00457/2008-004			
Number of Items for this Docket: 4 Percent of Total for this Docket: 24						
Work Planning & Practices / IR						
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00457/2008-004			
185 - Procedural adherence LTA	G - Engineering	F - Modification	050-00457/2008-004			
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00457/2007-006			
186 - Failure to take action / meet requirements	G - Engineering	F - Modification	050-00457/2008-004			
186 - Failure to take action / meet requirements	I - Instrumentation & Control	H - Health Physics	050-00457/2008-002			
186 - Failure to take action / meet requirements	I - Instrumentation & Control	T - Testing	050-00457/2008-002			
186 - Failure to take action / meet requirements	L - Licensing / regulatory affairs	A - Administrative	050-00457/2008-004			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00457/2008-002			
189 - Recognition of adverse condition / questioning attitude LTA	G - Engineering	F - Modification	050-00457/2008-004			
190 - Failure to stop work / non-conservative decision making	L - Licensing / regulatory affairs	A - Administrative	050-00457/2008-004			
Number of Items for this Docket: 10 Percent of Total for this Docket: 59						

05/29/2009 10:01:12 Page 14 of 226

Document Types: IR, LER From 01/01/2008 to 12/31/2008

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

	Avoided to colours 50			
	Facility Name: Browns Ferry 1 Docket (050- 00259)			
Details	Department	Work Type	Docket/Report	
Communication / IR				
160 - No communication / information not communicated	H - Health Physics	O - Control Room Ops	050-00259/2008-003	
160 - No communication / information not communicated	O - Operations	H - Health Physics	050-00259/2008-003	
Number of Items for this Docket: 2 Percent of Total for this Docket: 9				
Human-System Interface & Environmnt / IR				
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00259/2008-003	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 4				
Oversight / IR				
131 - Management expectations or directions LTA	G - Engineering	G - Design	050-00259/2008-003	
Number of Items for this Docket: 1 Percent of Total for this Docket: 4				
Problem Identification & Resolution / IR				
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2007-007	
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00259/2008-003	
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00259/2008-003	
146 - Evaluation LTA	G - Engineering	G - Design	050-00259/2007-007	
146 - Evaluation LTA	G - Engineering	H - Health Physics	050-00259/2008-003	
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2007-007	
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2007-007	
Number of Items for this Docket: 7 Percent of Total for this Docket: 30				
Work Planning & Practices / IR				
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00259/2007-007	
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2008-003	
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00259/2007-007	
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00259/2008-003	
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00259/2008-003	
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00259/2008-003	
187 - Action implementation LTA	G - Engineering	G - Design	050-00259/2007-007	
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00259/2008-003	
189 - Recognition of adverse condition / questioning attitude LTA	H - Health Physics	H - Health Physics	050-00259/2008-003	

05/29/2009 10:01:12 Page 15 of 226

Document Types: IR, LER From 01/01/2008 to 12/31/2008

Total Items for this Docket: 23

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Browns Ferry 1 Docket (050- 00259)					
Details	Department	Work Type	Docket/Report		
Work Planning & Practices / IR					
191 - Team interactions LTA	H - Health Physics	O - Control Room Ops	050-00259/2008-003		
191 - Team interactions LTA	O - Operations	H - Health Physics	050-00259/2008-003		
Number of Items for this Docket: 11 Percent of Total for this Docket: 48					
Problem Identification & Resolution / LER					
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2008-001-00		
Number of Items for this Docket: 1					
Percent of Total for this Docket: 4					