10/28/2014 16:58:38

Page 1 of 3

Document Types: IR, LER From 01/01/2009 to 12/31/2009

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 47
National Average: 46

2x National Average: 92 National Median: 23

Average for Selected Dockets: 47

Facility Name: Sequoyah 1 Docket (050- 00327)					
Details	Department	Work Type	Docket/Report		
Communication / IR					
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00327/2008-005		
160 - No communication / information not communicated Number of Items for this Docket: 2 Percent of Total for this Docket: 4	A - Administrative Support	A - Administrative	050-00327/2008-005		
Fitness for Duty / IR					
125 - Work hour control	O - Operations	O - Control Room Ops	050-00327/2009-004		
Number of Items for this Docket: 1 Percent of Total for this Docket: 2					
Human-System Interface & Environmnt / IR					
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	H - Health Physics	050-00327/2008-005		
Number of Items for this Docket: 1 Percent of Total for this Docket: 2					
Procedures & Reference Document / IR					
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00327/2009-004		
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00327/2008-005		
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00327/2008-005		
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00327/2009-006		
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00327/2009-004		
Number of Items for this Docket: 5 Percent of Total for this Docket: 11					
Problem Identification & Resolution / IR					
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00327/2009-003		
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00327/2009-004		
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00327/2009-004		
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00327/2009-006		
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00327/2009-006		
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00327/2009-006		
150 - Programmatic deficiency	I - Instrumentation & Control	H - Health Physics	050-00327/2008-005		
Number of Items for this Docket: 7 Percent of Total for this Docket: 15					

10/28/2014 16:58:38

Page 2 of 3

Document Types: IR, LER From 01/01/2009 to 12/31/2009

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 47
National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 47

	Facility Name: Sequoyah 1 D	Facility Name: Sequoyah 1 Docket (050- 00327)			
Details	Department	Work Type	Docket/Report		
Training / IR					
100 - Training LTA	T - Training	N - Training	050-00327/2009-004		
Number of Items for this Docket: 1 Percent of Total for this Docket: 2					
Work Planning & Practices / IR					
180 - Scheduling and planning LTA	O - Operations	O - Control Room Ops	050-00327/2009-004		
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00327/2009-004		
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00327/2009-004		
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00327/2009-003		
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00327/2009-004		
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00327/2008-005		
185 - Procedural adherence LTA	O - Operations	S - Surveillance	050-00327/2009-004		
186 - Failure to take action / meet requirements	C - Chemistry	Z - Other / Unknown	050-00327/2009-007		
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00327/2009-006		
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00327/2008-005		
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00327/2009-006		
187 - Action implementation LTA	G - Engineering	G - Design	050-00327/2009-003		
189 - Recognition of adverse condition / questioning attitude LTA	H - Health Physics	H - Health Physics	050-00327/2008-005		
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00327/2009-004		
193 - Non-conservative action	C - Chemistry	Z - Other / Unknown	050-00327/2009-007		
Number of Items for this Docket: 15 Percent of Total for this Docket: 32					
Oversight / LER					
130 - Inadequate suprevision / command and control	O - Operations	O - Control Room Ops	050-00327/2009-007-00		
130 - Inadequate suprevision / command and control	G - Engineering	G - Design	050-00327/2009-008-01		
Number of Items for this Docket: 2					
Percent of Total for this Docket: 4					
Procedures & Reference Document / LER					
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00327/2009-006-00		
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00327/2009-008-01		
Number of Items for this Docket: 2 Percent of Total for this Docket: 4					

10/28/2014 16:58:38

Page 3 of 3

Document Types: IR, LER From 01/01/2009 to 12/31/2009

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 47
National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 47

	Facility Name: Sequoyah 1 Docket (050- 00327)			
Details	Department	Work Type	Docket/Report	
Problem Identification & Resolution / LER				
146 - Evaluation LTA	F - Fuel Handling	R - Refueling	050-00327/2009-008-0	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 2				
Training / LER				
100 - Training LTA	G - Engineering	G - Design	050-00327/2009-008-01	
102 - Individual knowledge LTA	G - Engineering	G - Design	050-00327/2009-008-0	
Number of Items for this Docket: 2				
Percent of Total for this Docket: 4				
Work Planning & Practices / LER				
182 - Work package quality LTA	F - Fuel Handling	R - Refueling	050-00327/2009-008-0	
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00327/2009-007-00	
186 - Failure to take action / meet requirements	F - Fuel Handling	R - Refueling	050-00327/2009-008-0	
187 - Action implementation LTA	G - Engineering	G - Design	050-00327/2009-008-0	
188 - Work practice or craft skill LTA	F - Fuel Handling	R - Refueling	050-00327/2009-008-0	
189 - Recognition of adverse condition / questioning attitude LTA	P - Procedure Writers	P - Procedure Dev	050-00327/2009-006-00	
196 - Independent verification / plant tours LTA	F - Fuel Handling	R - Refueling	050-00327/2009-008-0	
197 - Self-check LTA	F - Fuel Handling	R - Refueling	050-00327/2009-008-0	
Number of Items for this Docket: 8				
Percent of Total for this Docket: 17				