03/16/2015 18:45:57

Page 1 of 2

Document Types: IR, LER From 01/01/2010 to 12/31/2010

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 35
National Average: 30
2x National Average: 60
National Median: 18

Average for Selected Dockets: 35

Facility Name: Turkey Point 3 Docket (050- 00250)				
Details	Department	Work Type	Docket/Report	
Communication / IR				
160 - No communication / information not communicated	L - Licensing / regulatory affairs	O - Control Room Ops	050-00250/2010-009	
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00250/2010-009	
160 - No communication / information not communicated	L - Licensing / regulatory affairs	O - Control Room Ops	050-00250/2010-009	
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00250/2010-009	
160 - No communication / information not communicated	A - Administrative Support	A - Administrative	050-00250/2009-005	
160 - No communication / information not communicated	A - Administrative Support	A - Administrative	050-00250/2009-005	
Number of Items for this Docket: 6 Percent of Total for this Docket: 17				
Oversight / IR				
130 - Inadequate suprevision / command and control	O - Operations	O - Control Room Ops	050-00250/2010-003	
Number of Items for this Docket: 1 Percent of Total for this Docket: 3				
Procedures & Reference Document / IR				
111 - Procedure / reference document technical content	F - Fuel Handling	R - Refueling	050-00250/2009-005	
111 - Procedure / reference document technical content	F - Fuel Handling	R - Refueling	050-00250/2009-005	
113 - Procedure / reference document development and maintenance L	O - Operations	O - Control Room Ops	050-00250/2010-009	
Number of Items for this Docket: 3  Percent of Total for this Docket: 9				
Problem Identification & Resolution / IR				
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00250/2010-009	
141 - Problem not properly classified or prioritized	Y - Shipping / transportation	Y - Shipping / transportatic	050-00250/2009-005	
141 - Problem not properly classified or prioritized	O - Operations	O - Control Room Ops	050-00250/2010-009	
142 - Operating experience (OE) review LTA	F - Fuel Handling	R - Refueling	050-00250/2009-005	
143 - Tracking / trending LTA	O - Operations	O - Control Room Ops	050-00250/2010-009	
146 - Evaluation LTA	F - Fuel Handling	R - Refueling	050-00250/2009-005	
148 - Action not yet started or untimely	O - Operations	O - Control Room Ops	050-00250/2010-009	
Number of Items for this Docket: 7				
Percent of Total for this Docket: 20				
Work Planning & Practices / IR				
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00250/2010-003	
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00250/2010-003	
186 - Failure to take action / meet requirements	F - Fuel Handling	R - Refueling	050-00250/2009-005	

03/16/2015 18:45:57

Page 2 of 2

Document Types: IR, LER From 01/01/2010 to 12/31/2010

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 35 National Average: 30 2x National Average: 60

National Median: 18
Average for Selected Dockets: 35

Facility Name: Turkey Point 3 Docket (050- 00250)				
Details	Department	Work Type	Docket/Report	
Work Planning & Practices / IR				
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00250/2010-003	
186 - Failure to take action / meet requirements	L - Licensing / regulatory affairs	O - Control Room Ops	050-00250/2010-009	
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00250/2010-003	
186 - Failure to take action / meet requirements	L - Licensing / regulatory affairs	A - Administrative	050-00250/2010-009	
186 - Failure to take action / meet requirements	F - Fuel Handling	R - Refueling	050-00250/2009-005	
187 - Action implementation LTA	F - Fuel Handling	R - Refueling	050-00250/2009-005	
187 - Action implementation LTA	A - Administrative Support	A - Administrative	050-00250/2009-005	
187 - Action implementation LTA	A - Administrative Support	A - Administrative	050-00250/2009-005	
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00250/2010-003	
190 - Failure to stop work / non-conservative decision making	H - Health Physics	H - Health Physics	050-00250/2010-003	
Number of Items for this Docket: 13 Percent of Total for this Docket: 37				
Procedures & Reference Document / LER				
110 - No procedure / reference documents	M - Mechanical	M - Maintenance / Repair	050-00250/2010-006-0	
111 - Procedure / reference document technical content	L - Licensing / regulatory affairs	A - Administrative	050-00250/2010-001-0	
Number of Items for this Docket: 2 Percent of Total for this Docket: 6				
Work Planning & Practices / LER				
180 - Scheduling and planning LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2010-006-0	
186 - Failure to take action / meet requirements	L - Licensing / regulatory affairs	A - Administrative	050-00250/2010-001-0	
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00250/2010-006-0	
Number of Items for this Docket: 3 Percent of Total for this Docket: 9				